

MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---|
| Date of Thorough Examination: 23/10/2023 | Report number: MP/52859/23/10/02 | Job no: 52859 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN NORTH LLC SULTANATE OF OMAN | | Address of premises at which the examination was made: SAFAH |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: | | |
| <p><u>MAIN HOOK</u></p> <p>Crane Reg No: 5431 MR</p> <p>Hook Owner Id: HBP-05</p> <p>Hook Serial No: 6J241</p> <p>Fleet No: TO 430</p> | | |
| Qty: 1nos | | |
| Date of Last MPI/ Cert No(If any): 20/10/2022; O/50174/22/10/03 | | |
| <p>Result of the above test :</p> <p>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</p> | | |

| | | |
|--|---|--|
| Inspected by, Name & Signature : MADHU |  | Latest date by which next MPI must be carried out: 22/04/2024 |
| Qualification : ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com |  | |