



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 26/10/2019	Report number: V/41594/19/10/03	Job no: 41594
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: SAFAH
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: MOBILE CRANE MAIN HOOK MPI		
Reg No : 5431MR		
OWNER'S ID NO:PLM430		
HOOK ID NO:HBP-05		
SERIAL NUMBER HOOK BLOCK:6J-241		
Qty: 1no.		
Date of Last MPI/ Cert No(If any): 31/12/2018 ; MP/39026/18/12/01		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Vijeesh Ravi 	Latest date by which next MPI must be carried out: 25/10/2020
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		