



## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 03/09/2019	Report number: MP/40940/19/09/32	Job no: 40940
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN (NORTH) SULTANATE OF OMAN	Address of premises at which the examination was made:  HAIMA	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b>KING PIN AND FILLET WELD</b>		
Make : JOST ( 3.5")		
Trailer Reg: 1280 BK		
Owner ID No. : TO 1850		
[I] shaped cylindrical king pin. Top head 114mm Intermediate 89mm Bottom head 111mm		
Qty: 1no		
Date of Last MPI/ Cert No( If any): N/A		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature :  Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out:  02/09/2020
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		