


**TA'AZEEZ ENTERPRISES LLC**Po Box: 23, Pc: 103-AL Qurum North AL Ghoubra- Bowsher
Sultanate Of Oman**MAGNETIC PARTICLE INSPECTION REPORT**

Company Name and Address TRUCK OMAN		Inspection Location HAIMA	
Certificate Number: MM.2766.10.25.04.42		Job No: 2766	
Date of Thorough Examination: 04.10.2025	Time of Inspection: 8.55	Issue Date: 08.10.2025	
Date of Previous MPI/ cert no: N/A		Date of Next Examination: 03.04.2026	
Description and identification of the equipment: 3.5" KNGPIN MPI			
REG NO: 1667 MA (TO 2433)			
Area Inspected (tick the appropriate box):			
☒ Weldment areas	☒ Stress Areas	☐ Full Body	☐ Others (top surface)
WHITE CONTRAST PAINT: ZCHEK WP		MAGNETISING METHOD: WET SUSPENSION BLACK INK	
BLACK MAGNETIC INK: ZCHEK 9E BLACK		ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
TEST METHOD: WET		MATERIAL: CARBON STEEL	
TEST TEMPERATURE: AMBIENT		SURFACE CONDITION: ACCEPTABLE	
TEST EQUIPMENT: PERMANENT MAGNET YOKE			
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION			

Inspected by : MALIK MOHAMMED	Company Stamp 
Qualifications: ASNT LEVEL II	
Signature: 	
Date: 08.10.2025	

If any Alteration/Major Repair is made, this certificate is rendered invalid.

This is to confirm that the item listed above was examined by the undersigned competent representative in compliance with the aforementioned standard. The aforementioned objects were found to be free of faults, deformations, and other problems at the time of inspection. The equipment is suitable for its intended use within the permitted limits, and at the time of inspection, it was determined to be suitable for continued use, provided that continuous maintenance is applied, qualified operators are employed, and our comments and recommendations are put into practice.