


MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|--|
| Date of Thorough Examination: 06/09/2020 | Report number: O/44490/20/09/05 | Job no: 44490 |
| Name and Address of the Owner of the Equipment TRUCK OMAN NORTH SULTANATE OF OMAN | | Address of premises at which the examination was made: ADAM |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: MAIN HOOK Make : TADANO (S.NO : 475443) Hook Serial no. : 2427/001 Reg no: 809 HK Crane Owner Id: PLM 1481 Qty: 1no. Date of Last MPI/ Cert No(If any): 2NA | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|--|---|---|
| Inspected by, Name & Signature : Koshy Mathew |  | Latest date by which next MPI must be carried out: 05/09/2021 |
| Qualification : ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | |  |

