



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 01.10.2025	Report number: AT5222.25.10.49	Job no: 5222
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: HAIMA	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: MAGNAVIS WCP	MAGNETISING METHOD: WET SUSPENSION BLACK INK	
BLACK MAGNETIC INK: MAGNAFLUX 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT:		
<u>KING PIN AND FILLET WELD</u> MAKE : JOST (3.5") TYPE: KZ14 TRAILER REG: 4929 ML FLEET NO: TO 1831 [I] SHAPED CYLINDRICAL KING PIN. TOP HEAD Ø114 mm INTERMEDIATE Ø89 mm BOTTOM HEAD Ø111 mm Qty: 1nos Date of Last MPI/ Cert No(If any): 16/04/2025 (MP/1205/25/04/022)		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Anoop Thankachan Qualification : ASNT L2		Latest date by which next MPI must be carried out: 30.03.2026
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		