

MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|--|---|
| Date of Thorough Examination: 01/07/2023 | Report number: MP/51274/23/07/24 | Job no: 51274 |
| Name and Address of the Owner of the Equipment TRUCK OMAN - NORTH SULTANATE OF OMAN | | Address of premises at which the examination was made: SAFAH |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others [TOP SURFACE ONLY] | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |

Description and identification of the equipment:

KING PIN AND FILLET WELD

Make : JOST (3.5")

Type : KZ 14

Trailer Reg: 620 DS / TO 239

[I] shaped cylindrical king pin.

Top head 114mmØ

Intermediate 89mmØ

Bottom head 111mmØ

Qty: 1 no

Date of Last MPI/ Cert No(If any):30/06/2022 ; MP/48939/30

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

| | | |
|--|---|---|
| Inspected by, Name & Signature : Madhu Pillai |  | Latest date by which next MPI must be carried out: 30/06/2024 |
| Qualification : ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | |  |

