الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/07/2023	Report number: MP/51274/23/07/42	Job no: 51274

Name and Address of the Owner of the Equipment	Address of premises at which the examination was made:
TRUCK OMAN - NORTH SULTANATE OF OMAN	SAFAH

Method: WET **Material: Carbon Steel** **Test temperature: Ambient**
Surface Condition: Acceptable **Equipment: Permanent magnet Yoke**

Area Inspected (tick the appropriate box):

☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [TOP SURFACE ONLY]

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

FIFTH WHEEL

Make: JOST

Type: JSK 38C

Reg no: 5572 RK / TO 1004

Qty: 1 no

Date of Last MPI/ Cert No(If any): 30/06/2022;MP/48939/11

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Madhu Pillai Qualification : ASNT L2		Latest date by which next MPI must be carried out: 01/07/2024
Name and address of employer of persons making and authenticating this report: **Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS** **P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.** **lifting@safetyoman.com**		SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED