



الشركة الفنية لخدمات السلامة والتجارة ش.م.م

SAFETY *technical* SERVICES & TRADING CO LLC

C.R. No.: 1/54421/7, Tel.: 00968 24502589 / 24596588 / Fax: 00968 24590272, P.O. Box 3288
 Seeb Code 111, Sultanate of Oman, E-mail: lifting-training@safetyoman.com / lifting-admin@safetyoman.com

TOS/SRQ/18/00076

Customer	TRUCK OMAN SOUTH	No. 37724
Name & Address	NIMR.	
Job Description	PLANT EQUIPMENT INSPECTION. MPI TEST AXLE SUPPORT STAND VISUAL	
Job Location	NIMR.	Date Started : 01/8/18
Special tools used (Load Cell)	N/A	Date Completed : 06/08/18
Certificates or Reports Issued	NO FOLLOW.	No. of Days : 6 days.
Comment on Job	FOCK LIFT VISUAL + MPI FOCK. 8 NOS. 427, 428, 887, 822 893, 894, 2521, 2522. CRANE VISUAL + MPI hook 1489, 2559, Lorry Loader VISUAL + MPI HOOR 2039, 2040, 12112 (3) WINCH VISUAL 21 NOS. 508, 787, 788, 789, 895, 896, 898, 899. 900, 901, 902, 904, 907, 2311, 2312, 2313, 205, 206, 212, 1009, 2003 KINGPIN, E20, 2642, 2693, 2694, 286, 287, 1613, 1615 (8)	Kilometers : — Travelling Time : — Originated From : — Telephone <input checked="" type="checkbox"/> Fax <input checked="" type="checkbox"/> Verbal <input type="checkbox"/> COST : 990 (16586)
<p>I confirm that the work carried out on my equipment by the lifting division of the Safety Technical Service has been completed to my satisfaction and (where necessary) correctly supervised. AND SKID TANKER MPI, AND LATHE m/c, welding m/c, AXLE SUPPORT STAND ALSO VISUAL INSPECTION.</p>		
Customer Representative :	Name of the Engineer :	
Signature : <i>K. Tagadeesh</i> 95328618	Signature : <i>M. ADHU</i>	

SPECIALIST: LIFTING EQUIPMENT MANUFACTURER, CRANE TESTING, SAFETY AUDITS, FIRST AID, FIRE AND SAFETY TRAINING