



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 26/04/2023	Report number: MP/50989/23/04/29	Job no: 50989
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SOUTH SULTANATE OF OMAN	Address of premises at which the examination was made: NIMR	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☒ Weldment areas ☐ Stress Areas ☒ Full Body ☐ Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>KING PIN AND FILLET WELD</u> Make : AL JABER (3.5") Trailer Reg: 2077 MH Fleet No. : TO-2690 [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ Qty: 1 no Date of Last MPI/ Cert No(If any): 21/05/2022; MP/48914/22/05/94		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 25/10/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

