



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: <b>22/05/2023</b>	Report number: <b>MP/51259/23/05/42</b>	Job no: <b>51259</b>
Name and Address of owner for whom the thorough examination was made: <b>TRUCK OMAN NORTH SULTANATE OF OMAN</b>	Address of premises at which the examination was made: <b>SAFAH</b>	
Method: <b>WET</b> Surface Condition: <b>Acceptable</b>	Material: <b>Carbon Steel</b> Equipment: <b>Permanent magnet Yoke</b>	Test temperature: <b>Ambient</b>
Area Inspected ( tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others		
WHITE CONTRAST PAINT: <b>Magnavis WCP</b>	MAGNETISING METHOD: <b>Wet suspension black ink</b>	
BLACK MAGNETIC INK: <b>Magnaflux 7HF</b>	ACCEPTANCE CODE: <b>ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1</b>	
Description and identification of the equipment: <b><u>FIFTH WHEEL</u></b> Make: <b>JOST</b> Type: <b>JSK 38C</b> Reg no: <b>9509 WK / TO 2303</b>  Qty: <b>1 no</b>  Date of Last MPI/ Cert No( If any): <b>26/05/2022; MP/48916/34</b>		
Result of the above test : <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : <b>Madhu Pillai</b>		Latest date by which next MPI must be carried out: <b>21/05/2024</b>
Qualification : <b>ASNT L2</b>		
Name and address of employer of persons making and authenticating this report: <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		