



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

eiaci  
LEEA  
154-IB  
Full Member  
جامعة المؤسسات العالمية للمعايير  
Emirates International Accreditation Centre

AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

### CERTIFICATE OF THOROUGH EXAMINATION AND TEST

**Certificate No: MP/43698/20/07/07**

**Date of Inspection: 08/07/2020**

Name and Address of the Owner:	TRUCK OMAN
Maker & Date of Manufacture:	TOYOTA ; 1997
Place of Inspection:	NIMR
Ref. Standard:	ISO22915-2 /BS EN 1459/SP 2275
Registration No. & Owner No.:	5285 HW ; TO-804
Model No. and Serial No.:	FD 30 ; 31216
Running hours:	15995 hrs.
Manufacturer's documentation:	IN SERVICE EQUIPMENT
Date of Previous inspection / cert no:	1301/2020; A/41848/20/01/07
Date of Next inspection:	07/01/2021
Date of Previous load test / cert no:	17/07/2019 (A/40300/19/07/16)
Date of Next load test:	16/07/2023
Availability of operations manual in cabin:	Yes
Availability of daily check report:	Yes

**Description**

Diesel powered counter balance forklift truck with side shifter. SWL: 2500 kg @ 600mm load center.

#### Test carried out according to tabulated column

Description of test:	Test load applied	S.W.L
	In kgs	In kgs
Visual inspection, Functional test & Load test carried out.		
Max. Lifting Height: 3500mm		
Hydraulic creep : Nil		
FORK S/N – MTS – 7737 & MTS - 7776	---	2.5 t @500 mm Load Center

**Conclusion: Fit for its intended use at the time of inspection.**

*This certificate becomes invalid if any Alteration/Major Repair and modification is done.*

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature: Mr. Gishin Thomas



Inspected by, Name & Signature: Madhu Pillai



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

eiaci  
LEEA  
154-IB  
Full Member  
الإمارات للجودة  
Emirates International Accreditation Centre

### Annexure of certificate of test & thorough examination of Fork lift

**Certificate No: MP/43698/20/07/07**

**Date of Inspection: 08/07/2020**

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	S	
Masts and Back rest , carriage	S	
Forks and its extensions, slide end stopper, locks	S	
Load chain and its assemblies	S	
Side rollers and roll over cage	S	
Safety devices	S	
Battery and its connections	S	
Hydraulic system & hoses and end fittings	S	
Electrical system & Cables	S	
Cooling system	S	
Steering function	S	
All controls levers function & symbols legible	S	
Capacity plate in place and legible	S	
All gauges in cab	S	
Over head & foot guard	S	
Exhaust system	S	
Side shifting function (if applicable)	S	
Horn, reverse alarm, rotating warning light	S	
Lights & indicators	S	
Seat and seat belts	S	
Parking brake and foot brake function	S	
Fire extinguisher	S	
MPI fork blades, date / report nr. (annually)	S	05/03/2019
Mast disassembly (every 4 years)	NA	
General condition	S	
Display markings (SWL, tire pressure, insp. date, due date)	S	
S- Satisfactory    NS-Not Satisfactory    NA-Not applicable    NP-Not provided by OEM    SC- See Comments		
Details of tools/equipments used: STS-LD-65; STS-LD-75		
<b>General comments: NONE</b>		

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

