



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

eiaci
مكتب الإمارات العربي للاعتماد
Emirates International Accreditation Centre
154-IB

AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

CERTIFICATE OF THOROUGH EXAMINATION AND TEST OF MEWP

Date of Thorough Examination: 05/08/2021	Report number: V/46984/21/08/119	Job no: 46984
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: NIMR	
Description and identification of the equipment: <u>Diesel Powered Hydraulically Operated Man lift Mounted On Truck</u>		Test Load
Make : CTE Model no. : CTE Z 20E Serial no. : 9642 Fleet no. : TO 2502 Reg. No. : 2199 YW Year of Manufacture : 2016 Hour Meter: NA Max Height from Ground : 17.8 m Max Out Reach : 9m Max Allowable Wind Speed : 12.5 M/S		SWL --- 200 Kg (80+80+40+ 2 Persons + Tools)
Visual inspection and Functional test carried out.		
Date of Previous Examination/ cert no: 13/02/2021; MP/45694/21/02/52	Date of Next Examination: 04/02/2022	
Date of previous Load test/ Cert no: 13/02/2021; MP/45694/21/02/52	Date of Next Load test: 12/02/2022	
Ref. Standards: BS EN 280 , SP2275		
Comments(If any) : REFER ANNEX		
RESULT: The above mentioned equipment was found to be in order for its intended use at the time of inspection.		
<i>This certificate becomes invalid if any Alteration/Major Repair and modification is done.</i>		
This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.		

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: George





الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

eiaci
مكتب الإمارات العربي للاعتماد
Emirates International Accreditation Centre
154-IB

Annexure of certificate of test & thorough examination of MEWP

Certificate No: V/46984/21/08/119

Date of Inspection: 05/08/2021

Status Legend: S- Satisfactory NA-Not applicable F-Findings CF-Critical Findings						
No.	Description	Status	No.	Description	Status	
1	Operations Manual/Catalogue	S	22	Emergency stop button	S	
2	Monthly Inspection record	S	23	Boom/ Extending structure	S	
3	Maintenance records	S	24	Travelling	S	
4	OEM Specification plate	S	25	Brakes	S	
5	Hydraulic tank	S	26	Slew ring and slewing	S	
6	Hydraulic hoses and fittings	S	27	Emergency lowering system	S	
7	Hydraulic cylinders	S	28	Travelling/Descent alarm	S	
8	Tire/Tracks (Rim,bolts)	S	29	Inclination limit (as per OEM)	S	
9	Chassis/Axle (Bolts, leaks)	S	30	Pothole guard	NA	
10	Engine condition	S	31	Horn	S	
11	Engine covers and guards	S	32	Warning signals / safety markings	S	
12	Power supply / Electrical cables	S	33	Lightings / Revolving beacon	S	
13	Battery-terminal and condition	S	34	Spark arrestor (if required)	NA	
14	Fluid levels(Oil,coolant,Fuel)	S	35	Fire extinguisher	S	
15	Fluids leakages	S	36	Full functional test	S	
16	Platform condition	S	37	Rated load test	NA	
17	Harness anchorage point	S	38	Overload test	NA	
18	Access gate	S	39	NDT(If applicable)	NA	
19	Handrails/ Toe guard	S	40	Other Test (If applicable)	NA	
20	Identification of control levers	S	41	General Condition	S	
21	Platform rotation	S				

Details of tools/equipments used:

Findings/Critical Findings Report

F/CF	No.	Remarks

