



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

|                                                                                                                                                                                                                                                                                                                                                     |                                                                 |                           |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------|---------------------------|
| Date of Thorough Examination:<br>14/07/2021                                                                                                                                                                                                                                                                                                         | Report number:<br>MA/46788/21/07/28                             | Job no:<br>46788          |
| Name and Address of the Owner of the Equipment<br>TRUCK OMAN - NORTH<br>SULTANATE OF OMAN                                                                                                                                                                                                                                                           | Address of premises at which the examination was made:<br>SAFAH |                           |
| Method: WET<br>Surface Condition: Acceptable                                                                                                                                                                                                                                                                                                        | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke      | Test temperature: Ambient |
| Area Inspected ( tick the appropriate box):<br><input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE ONLY ]                                                                                                                     |                                                                 |                           |
| WHITE CONTRAST PAINT: Magnavis WCP                                                                                                                                                                                                                                                                                                                  | MAGNETISING METHOD: Wet suspension black ink                    |                           |
| BLACK MAGNETIC INK: Magnaflux 7HF                                                                                                                                                                                                                                                                                                                   | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1         |                           |
| Description and identification of the equipment:<br><u>FIFTH WHEEL</u><br>Make: JOST<br>Type: JSK 38C<br>Serial no: 11382846-63<br>Reg no: 6556 HM / 2301<br><br>Qty: 1 no<br>Date of Last MPI/ Cert No( If any): N/A<br>Result of the above test :<br>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION |                                                                 |                           |

|                                                                                                                                                                                                                                                                        |  |                                                                  |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------|
| Inspected by, Name & Signature :<br>Vijeesh Ravi<br>Qualification : ASNT L2                                                                                                                                                                                            |  | Latest date by which next MPI must be carried out:<br>13/07/2022 |
| Name and address of employer of persons making and authenticating this report:<br>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS<br>P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a> |  |                                                                  |

