


AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

CERTIFICATE OF THOROUGH EXAMINATION AND TEST OF MEWP

Date of Thorough Examination: 22/03/2023		Report number: MP/50972/23/03/01		Job no: 50972	
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN			Address of premises at which the examination was made: NIMR		
Description and identification of the equipment: <u>Diesel Powered Hydraulically Operated Man lift Mounted On Truck</u> Make : CTE Model no. : CTE Z 20E Serial no. : 9641 Fleet no. : TO 2503 Reg. No. : 1597 MH Year of Manufacture : 2016 Hour Meter: NA Max Height from Ground : 17.8 m Max Out Reach : 9m Max Allowable Wind Speed : 12.5 M/S Visual inspection and Functional Test and Load Test Carried Out.				Test Load	SWL
				----	200 Kg (80+80+40+ 2 Persons + Tools)
Date of Previous Examination/ cert no: 06/01/2023; MP/49842/23/01/13			Date of Next Examination: 21/09/2023		
Date of previous Load test/ Cert no: 16/07/2022; MP/48942/22/07/138			Date of Next Load test: 15/07/2023		
Ref. Standards: BS EN 280 , SP2275					
Comments(If any) : REFER ANNEX					
RESULT: The above mentioned equipment was found to be in order for its intended use at the time of inspection.					
<i>This certificate becomes invalid if any Alteration/Major Repair and modification is done.</i>					
This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.					

Approved by, Name & Signature: Infanso Oswin

Inspected by, Name & Signature: Madhu Pillai





AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

ANNEXURE OF CERTIFICATE OF TEST & THOROUGH EXAMINATION OF MEWP

Certificate No: MP/50972/23/03/01

Date of Inspection: 22/03/2023

Status Legend: S- Satisfactory NA-Not applicable F-Findings CF-Critical Findings					
No.	Description	Status	No.	Description	Status
1	Operations Manual/Catalogue	F	22	Emergency stop button	S
2	Monthly Inspection record	S	23	Boom/ Extending structure	S
3	Maintenance records	S	24	Travelling	S
4	OEM Specification plate	S	25	Brakes	S
5	Hydraulic tank	S	26	Slew ring and slewing	S
6	Hydraulic hoses and fittings	S	27	Emergency lowering system	S
7	Hydraulic cylinders	S	28	Travelling/Descent alarm	S
8	Tire/Tracks (Rim, Bolts)	S	29	Inclination limit (as per OEM)	S
9	Chassis/Axle (Bolts, leaks)	S	30	Pothole guard	NA
10	Engine condition	S	31	Horn	S
11	Engine covers and guards	S	32	Warning signals / safety markings	S
12	Power supply / Electrical cables	S	33	Lightings / Revolving beacon	S
13	Battery-terminal and condition	S	34	Spark arrestor (if required)	NA
14	Fluid levels(Oil, Coolant, Fuel)	S	35	Fire extinguisher	S
15	Fluids leakages	S	36	Full functional test	S
16	Platform condition	S	37	Rated load test	NA
17	Harness anchorage point	S	38	Overload test	NA
18	Access gate	S	39	NDT(If applicable)	NA
19	Handrails/ Toe guard	S	40	Other Test (If applicable)	NA
20	Identification of control levers	S	41	General Condition	S
21	Platform rotation	S			
Details of tools/equipment's used: STS-LD-,75,58,73,80					
Findings/Critical Findings Report					
F/CF	No.	Remarks			
F	1	Provide Manual /Catalogue			

