

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 24/06/2023	Report number: MP/51271/23/06/13	Job no: 51271
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: NIMR

Method: WET Material: Carbon Steel Test temperature: Ambient
Surface Condition: Acceptable Equipment: Permanent magnet Yoke

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others

WHITE CONTRAST PAINT: Magnavis WCP MAGNETISING METHOD: Wet suspension black ink

BLACK MAGNETIC INK: Magnaflux 7HF ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

Hook MPI On Lorry Loader Crane

Reg. No. : 6040 YW

Owners ID No. : TO-2022

Crane Serial no. : 16613410

+

Qty: 1no.

Date of Last MPI/ Cert No (If any): MP/48942/22/07/20

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: AFTER ONE YEAR AS PER CLIENT REQUIREMENT OR AT THE DISCRETION OF THE LIFTING INSPECTOR
--	---	--

Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com	
--	---

