الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 12/04/2021	**Report number:** O/46139/21/04/36	**Job no:** 46139

Name and Address of owner for whom the thorough examination was made: **TRUCK OMAN** **SULTANATE OF OMAN**	**Address of premises at which the examination was made:** **NIMR**

Method: WET **Material: Carbon Steel** **Test temperature: Ambient**
Surface Condition: Acceptable **Equipment: Permanent magnet Yoke**

Area Inspected (tick the appropriate box):

☐ Weldment areas ☑ Stress Areas ☑ Full Body ☐ Others

WHITE CONTRAST PAINT: Magnavis WCP	**MAGNETISING METHOD: Wet suspension black ink**
BLACK MAGNETIC INK: Magnaflux 7HF	**ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1**

Description and identification of the equipment:

<u>Hook MPI On Lorry Loader Crane</u>

Reg. No. : 5680 YW

Owner ID No. : TO-2046

Crane Serial no. : 178CX00174

Qty: 1nos

Date of Last MPI/ Cert No (If any): 05/05/2020; MP/43676/20/05/41

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : **Koshy Mathew** **Qualification : ASNT L2**	Koshy	**Latest date by which next MPI must be carried out:** **After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector**
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED