



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 11/02/2023	Report number: A/50824/23/02/45	Job no: 50824
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: HAIMA	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☐ Weldment areas ☐ Stress Areas ☐ Full Body ☒ Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: FIFTH WHEEL Make : JOST Type: JSK38C Serial no; 2163022876 Reg No: 7817 ML Id no: TO 2008 Qty: 1no. Date of Last MPI/ Cert No(If any): 07/02/2022; MP/48120/22/02/19		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 10/02/2024
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

