

MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|---|--|
| Date of Thorough Examination: 18/08/2023 | Report number: MP/51293/23/09/03 | Job no: 51293 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SOUTH SULTANATE OF OMAN | | Address of premises at which the examination was made: NIMR |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>HOOK MPI ON LORRY LOADER CRANE</u> | | |
| Reg. No. : 3873 DS | | |
| Owners ID No. : TO-922 | | |
| Crane Serial no. : 100113753 | | |
| Qty: 1no | | |
| Date of Last MPI/ Cert No(If any): 28/09/2022;A/49876 | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by, Name & Signature : MOHAMMED ANAZ |  | Latest date by which next MPI must be carried out: 17/08/2024 |
| Qualification : ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com |  | |

