

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 16/09/2020	Report number: O/44494/20/09/08	Job no: 44494
Name and Address of the Owner of the Equipment  TRUCK OMAN SOUTH SULTANATE OF OMAN		Address of premises at which the examination was made:  NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  FORKS HEEL, UPPER & LOWER HOOKS		
Forklift Details:  Make : Caterpillar Model no. : DP 50 NT Serial no.: CT-28C-50371 Owner ID : TO-2530 Reg. No. : 5156 RA		
Fork Details:  Fork ID : 1509300 & 1501394A Qty: 1 pair		
Date of Last MPI/ Cert No( If any): NA		
Result of the above test :  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Koshy Mathew		Latest date by which next MPI must be carried out: 15/09/2021
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

