

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 15/07/2022	Report number: MP/48942/22/07/02	Job no: 48942
Name and Address of the Owner of the Equipment  TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made:  NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FORKS HEEL , UPPER &amp; LOWER HOOKS</u>		
<u>Forklift Details:</u>  Make : Caterpillar Model no. : 930 K Serial no.: CAT0930KJDYB00362 Owner ID : TO 2531 Reg. No. : 5157 RA		
<u>Fork Details:</u>  Fork ID : 1997393 – L1 & 1997394-L1 Qty: 1 pair Date of Last MPI/ Cert No ( If any): 21/08/2021 ; V/46984/63		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out:  After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

