

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 24/01/2022		Report number: MP/48110/22/01/115		Job no: 48110	
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN			Address of premises at which the examination was made: NIMR		
Method: WET Surface Condition: Acceptable		Material: Carbon Steel Equipment: Permanent magnet Yoke		Test temperature: Ambient	
Area Inspected (tick the appropriate box): ☐ Weldment areas ☐ Stress Areas ☐ Full Body ☒ Others [TOP SURFACE ONLY]					
WHITE CONTRAST PAINT: Magnavis WCP			MAGNETISING METHOD: Wet suspension black ink		
BLACK MAGNETIC INK: Magnaflux 7HF			ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1		
Description and identification of the equipment: <u>FORKS</u> Make : CATERPILLAR Model No.: DP100NM1 ID No.: TO-2535 Reg. No. : 7988 DS Fork Dimension: L X W X H: 3500mm x 180mm x 933mm Qty: 1no. Date of Last MPI/ Cert No(If any): 07/02/2021; MP/45962/21/02/49					
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION					

Inspected by, Name & Signature : Madhu Pillai Qualification : ASNT L2		Latest date by which next MPI must be carried out: 23/01/2023
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

