



الشركة الفنية لخدمات السلامة ش.م.م  
**SAFETY technical SERVICES CO . LTD.**

TEL.: 00968 24502588/24502589, FAX: 00968 24590272, P.O. BOX 3288  
SEEB CODE 111, SULTANATE OF OMAN, E-MAIL: safety@omantel.net.om / lifting@safetyoman.com

Customer	TRUCK OMAN (SOUTH)	No. 35486
Name & Address	P. O. BOX 362 P. C. 116	
Job Description	MEWP, FORKLIFT VISUAL INSPECTION	
Job Location	NIMR. G. E YARD	Date Started : 17/10/17
Special tools used (Load Cell)	N/A	Date Completed : 17/10/17
Certificates or Reports Issued	TO FOLLOW.	
Comment on Job	3 NOS MEWP VISUAL INSPECTION TO.2498 (16/10/17) TO.2499, TO.2500. ONE NO FORKLIFT VISUAL INSPECTION. TO.2535. SATISFACTOR AT THE TIME OF TEST (15/10/17)	
I confirm that the work carried out on my equipment by the lifting division of the Safety Technical Service has been completed to my satisfaction and (where necessary) correctly supervised.		Kilometers : — Travelling Time : — Originated From : Telephone <input checked="" type="checkbox"/> Fax <input type="checkbox"/> Verbal <input type="checkbox"/> COST : Signature : <u>Sanjeev Ramal</u>
Customer Representative :	Name of the Engineer : <u>maelha</u>	
Signature : <u>Sanjeev</u>	Signature : <u>Reeth</u>	