

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 20.12.2025	Report number: AT6708.25.12.69	Job no: 6708
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: FAHUD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>Fork Heel Top & Bottom Hook Welds</u>		
Reg. No. : 9774 WB		
Fleet No. : TO-821		
ID No. : 4350 – 24 (PAIR)		
Fork Dimension : 1200 x 120 x 800mm (L x W x H)		
Qty: 1 PAIR		
Date of Last MPI/ Cert No (If any): 20.12.2025 (AT4459.25.05.197)		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Qualification : ASNT L2	Anoop Thankachan 	Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		