

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 22/11/2021	Report number: MP/47723/21/11/11	Job no: 47723
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SOUTH SULTANATE OF OMAN		Address of premises at which the examination was made:  NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FORK HEEL AND HOLDING BRACKET</u>		
<u>Forklift Details:</u> Make : JCB Owner ID : PLM-887 Reg. No. : 6682 WK		
<u>Fork Details:</u> Fork S/N : 1030772-C11 (PAIR)		
Qty: 1 pair		
Date of Last MPI/ Cert No( If any): 11/12/2020; MP/44816/20/12/31		
<u>Result of the above test :</u>  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature: Madhu Pillai  Qualification : ASNT L2		Latest date by which next MPI must be carried out: 21/11/2022
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		