

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 08/11/2022	Report number: MP/49818/22/11/06	Job no: 49818
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SOUTH SULTANATE OF OMAN		Address of premises at which the examination was made: NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p><u>FORK HEEL AND HOLDING BRACKET</u></p> <p><u>Forklift Details:</u> Make : JCB</p> <p>Owner ID : PLM-887 Reg. No. : 6682 WK</p> <p><u>Fork Details:</u></p> <p>Fork S/N : 1030772-C11 (PAIR)</p> <p>Qty: 1 pair</p>		
Date of Last MPI/ Cert No(If any): 22/11/2021; MP/47723/21/11/11		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature: Madhu Pillai		Latest date by which next MPI must be carried out: 07/11/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		