

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 11/02/2023	Report number: A/50824/23/02/53	Job no: 50824
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>FIFTH WHEEL</u>		
Make : JOST		
Type: JSK38C1		
Serial no; 2163252597		
Reg No: 5863 DS		
Id no: TO 1013		
Qty: 1no.		
Date of Last MPI/ Cert No(If any): 07/02/2022; MP/48120/22/02/17		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 10/02/2024
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

