

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 11.07.2025	Report number: AT4482.25.07.17	Job no: 4482
Name and Address of the Owner of the Equipment  TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made:  HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:  <b>FIFTH WHEEL</b> Make: JOST Type: JSK 38C1 Serial No; 2163252597 Reg no: 5863 DS Owner ID: TO 1013 Qty: 1 no Date of Last MPI/ Cert No (If any): 17/01/2025 (MP/1181)		
Result of the above test:  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by Name & Signature: Anoop Thankachan  Qualification: ASNT L2		Latest date by which next MPI must be carried out:  10.01.2026
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		