

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 10/07/2020	Report number: MP/43698/20/07/51	Job no: 43698
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>FORK HEEL & HOLD BRACKET</u>		
ID No. : TO-2521		
Reg. No. : 4968 HW		
Fork Dimension : L-1200 x W-125 x Thk-50mm		
Fork serial no: 2394252 (L8) 2418896 (L1)		
Qty: 1no		
Date of Last MPI/ Cert No(If any): 16/07/19; A/40300/19/07/13		
Result of the above test : <u>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</u>		

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 09/07/2021
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

