



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: O/44494/20/09/15

Date of Inspection: 16/09/2020

Name and Address of the Owner:	TRUCK OMAN (SOUTH)	
Maker & Date of Manufacture:	CATERPILLAR ; 2014	
Place of Inspection:	NIMR	
Ref. Standard:	BS ISO 2330/BS EN 474-3/SP 2275	
Registration No. & Owner No.:	4953 RK ; TO-2528	
Model No. and Serial No.:	930K ; CAT0930KTEYE00545	
Running hours:	8964 hrs.	
Manufacturer's documentation:	In service equipment	
Date of Previous inspection / cert no:	22/03/2020; A/43457/20/03/13	
Date of Next inspection:	15/03/2021	
Date of Previous load test / cert no:	05/04/2019 ; MP/40158/19/04/34	
Date of Next load test:	04/04/2023	
Availability of operations manual in cabin:	Available	
Availability of daily check report:	Available	
Description Diesel powered hydraulic Operated articulated wheel loader c/w forks SWL On Firm Level Ground 5213 Kg & On Rough Terrain 3910 Kg @ 600 mm Load Center		
Test carried out according to tabulated column		
Description of test:	Test load applied In kgs	S.W.L In kgs
Visual inspection, Functional test & Load test carried out.		
Max. Lifting Height: 3693 mm		
Hydraulic creep : Nil	5700 Kg	5213 KG @ Firm Level Ground
Fork Serial No: 1928914-L1 (Pair)	4300 Kg	3910 Kg @ Rough Terrain
Conclusion: Fit for its intended use at the time of inspection.		
<i>This certificate becomes invalid if any Alteration/Major Repair and modification is done.</i>		
This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.		

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin



Ref: STSI-FMT-03 Rev.00 Date: 18.02.2020

1 / 2



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS



Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

Annexure of certificate of test & thorough examination

Certificate No: O/44494/20/09/15

Date of Inspection: 16/09/2020

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	S	
Masts and Back rest , carriage	S	
Forks and its extensions, slide end stopper, locks	S	
Load chain and its assemblies	NA	
Side rollers and roll over cage	NA	
Safety devices	NA	
Battery and its connections	S	
Hydraulic system & hoses and end fittings	S	
Electrical system & Cables	S	
Cooling system	S	
Steering function	S	
All controls levers function & symbols legible	S	
Capacity plate in place and legible	S	
All gauges in cab	S	
Over head & foot guard	S	
Exhaust system	S	
Side shifting function (if applicable)	NA	
Horn, reverse alarm, rotating warning light	S	
Lights & indicators	S	
Seat and seat belts	S	
Parking brake and foot brake function	S	
Fire extinguisher	S	
MPI fork blades, date / report nr. (annually)	S	29/09/2019; A/40738
Mast disassembly (every 4 years)	NA	
General condition	S	
Display markings (SWL, tire pressure, insp. date, due date)	S	
S- Satisfactory NS-Not Satisfactory NA-Not applicable NP-Not provided by OEM SC- See Comments		
Details of tools/equipments used: STS-LD-63; STS-VC7949		
General comments: Finding Rated Capacity Of Pallet Fork Given By The Manufacturer On Page 68		

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

