

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 25/04/23	Report number: MP/50989/23/04/13	Job no: 50989
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SOUTH SULTANATE OF OMAN		Address of premises at which the examination was made:  NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FORK HEEL , TOE , UPPER &amp; BOTTOM HOOKS</u>		
Make : caterpillar		
Id No. : To-822		
Reg. No. : 9775 WB		
Owner ID No. : 2445853 (pair)		
Qty: 1no.		
Date of Last MPI/ Cert No( If any): 21/05/2022 , MP/48914/22/05/175		
Result of the above test :  <u>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</u>		

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out:  After one year as per client requirement or at the discretion of lifting inspector
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

