



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 27.09.2025	Report number: AT5221.25.09.04	Job no: 5221
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SOUTH SULTANATE OF OMAN	Address of premises at which the examination was made:  Fahud	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment: <u>Fork Heel, Toe, Upper &amp; Bottom Hooks</u> Make: Caterpillar Reg. No.: 9775 WB ID No: TO-822 Fork Serial No: 2445853(PAIR) Qty: 1 PAIR Date of Last MPI/ Cert No (If any): 14/03/2025 (MP/1197/25/03/238)		
Result of the above test: <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature: Anoop Thankachan  Qualification: ASNT L2		Latest date by which next MPI must be carried out:  After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		