



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

eiaci
LEEA
154-IB
Full Member
إعتماد الهيئات المختصة للدول العربية
Emirates International Accreditation Centre

AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: MP/43698/20/07/05

Date of Inspection: 08/07/2020

Name and Address of the Owner:	TRUCK OMAN
Maker & Date of Manufacture:	CATERPILLAR ; 2007
Place of Inspection:	NIMR
Ref. Standard:	ISO22915-2 /BS EN 1459/SP 2275
Registration No. & Owner No.:	9775 WB ; TO-822
Model No. and Serial No.:	930G ; CAT0930GJTWR02865
Running hours:	15072 hrs.
Manufacturer's documentation:	IN SERVICE EQUIPMENT
Date of Previous inspection / cert no:	13/01/2020; A/41848/05
Date of Next inspection:	07/01/2021
Date of Previous load test / cert no:	03/03/2017 ; MP/33390/17/03/25
Date of Next load test:	02/03/2021
Availability of operations manual in cabin:	Yes
Availability of daily check report:	Yes

Description

Diesel powered hydraulically operated articulated Wheel Loader c/w fork SWL-5.1 t @ 600mm load center. Static tipping load @ full 40° turn is 6.3 t.

Test carried out according to tabulated column

Description of test:	Test load applied	S.W.L
	In kgs	In kgs
Visual inspection, Functional test Carried out		
Max Lifting Height : 4000mm		
FORK S/N – J813 – C1B3 (PAIR)	---	5.1t @ 600 mm Load Center

Conclusion: Fit for its intended use at the time of inspection.

This certificate becomes invalid if any Alteration/Major Repair and modification is done.

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature: Mr. Gishin Thomas



Inspected by, Name & Signature: Madhu Pillai



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



Annexure of certificate of test & thorough examination of Fork lift

Certificate No: MP/43698/20/07/05

Date of Inspection: 08/07/2020

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	S	
Masts and Back rest , carriage	S	
Forks and its extensions, slide end stopper, locks	S	
Load chain and its assemblies	NA	
Side rollers and roll over cage	NA	
Safety devices	NA	
Battery and its connections	S	
Hydraulic system & hoses and end fittings	S	
Electrical system & Cables	S	
Cooling system	S	
Steering function	S	
All controls levers function & symbols legible	S	
Capacity plate in place and legible	S	
All gauges in cab	S	
Over head & foot guard	S	
Exhaust system	S	
Side shifting function (if applicable)	NA	
Horn, reverse alarm, rotating warning light	S	
Lights & indicators	S	
Seat and seat belts	S	
Parking brake and foot brake function	S	
Fire extinguisher	S	
MPI fork blades, date / report nr. (annually)	S	16/07/19
Mast disassembly (every 4 years)	NA	
General condition	S	
Display markings (SWL, tire pressure, insp. date, due date)	S	
S- Satisfactory NS-Not Satisfactory NA-Not applicable	NP-Not provided by OEM	SC- See Comments
Details of tools/equipments used: STS-LD-65; STS-LD-75		
General comments: NONE		

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

