



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 20.12.2025	Report number: AT6708.25.12.31	Job no: 6708
Name and Address of the Owner of the Equipment: TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: FAHUD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☐ Weldment areas ☐ Stress Areas ☐ Full Body ☒ Others [TOP SURFACE]		
WHITE CONTRAST PAINT: Magnavis WCP		MAGNETISING METHOD: Wet suspension black ink
BLACK MAGNETIC INK: Magnaflux 7HF		ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
Description and identification of the equipment: <u>FIFTH WHEEL</u> Make: JOST Model No.: JSK 38 C Serial no.: 2163262532 Reg. No.: 1263 YD Owner ID: TO 904 Qty: 1no Date of Last MPI/ Cert No (If any): 03.07.2025 (AT4480.25.07.25)		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature: Anoop Thankachan Qualification: ASNT L2		Latest date by which next MPI must be carried out: 19.06.2026
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		