

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 18/08/2023	Report number: MP/51293/23/08/04	Job no: 51293
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SOUTH SULTANATE OF OMAN		Address of premises at which the examination was made: NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:		
<p>Crane Main Hook</p> <p>Hook Serial No : 2971/17/7-14</p> <p>Reg. No Crane : 1400 HA</p> <p>Owners Id No: TO 2563</p>		
<p>Qty: 1 no.</p> <p>Date of Last MPI/ Cert No(If any): 28/09/2022; A/49876</p> <p>Result of the above test :</p> <p>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</p>		
Inspected by, Name & Signature : MOHAMMED ANAZ		Latest date by which next MPI must be carried out: 17/08/2024
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

