الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

# MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|---|---|
| **Date of Thorough Examination:** 30/06/2022 | **Report number:** MP/48939/22/06/06 | **Job no:** 48939 |
| **Name and Address of the Owner of the Equipment**<br><br>TRUCK OMAN - NORTH<br>SULTANATE OF OMAN | **Address of premises at which the examination was made:**<br>SAFAH | |

**Method: WET** **Material: Carbon Steel** **Test temperature: Ambient**
**Surface Condition: Acceptable** **Equipment: Permanent magnet Yoke**

**Area Inspected ( tick the appropriate box):**

☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [ TOP SURFACE ONLY ]

| | |
|---|---|
| **WHITE CONTRAST PAINT: Magnavis WCP** | **MAGNETISING METHOD: Wet suspension black ink** |
| **BLACK MAGNETIC INK: Magnaflux 7HF** | **ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1** |

**Description and identification of the equipment:**

**FIFTH WHEEL**

**Make: JOST**

**Type: JSK 38C**

**Serial no: 90151870012**

**Reg no: 5841 MA / TO 2310**

**Qty: 1 no**

**Date of Last MPI/ Cert No( If any): 14/07/2021 ; MA/46788/34**

**Result of the above test :**

**MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION**

| | | |
|---|---|---|
| **Inspected by, Name & Signature :**<br>**Madhu Pillai**<br><br>**Qualification : ASNT L2** | | **Latest date by which next MPI must be carried out:**<br><br>**29/06/2023** |
| **Name and address of employer of persons making and authenticating this report:**<br><br>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS<br>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.<br>lifting@safetyoman.com | | SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED |