

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 19.12.2025	Report number: AT6708.25.12.18	Job no: 6708
Name and Address of the Owner of the Equipment:  TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made:  FAHUD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FIFTH WHEEL</u>  Make: JOST  Model No.: JSK 38 C  Serial no.: 1863443488  Reg. No.: 1249AD  Owner ID: TO 900  Qty: 1no		
Date of Last MPI/ Cert No (If any): 03.07.2025 (AT4480.25.07.20)		
Result of the above test:  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature: Anoop Thankachan  Qualification: ASNT L2		Latest date by which next MPI must be carried out: 18.06.2026
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		