



MAGNETIC PARTICLE INSPECTION REPORT

Date of Through Examination: 09/12/2018	Report number: A/38650/18/12/07	Job no: 38650
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN (SOUTH) SULTANATE OF OMAN		Address of premises at which the examination was made: HARWEEL
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>CRANE HOOK (MAIN)</u> Make : TADANO YOM : 2008 Hook Serial no. :M-7Z21 Owner ID No. : TS-703		
Qty: 1no.		
Date of Last MPI/ Cert No(If any): 27/01/2015 ; A/38437/15/1/31		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Mohammed Anaz 	Latest date by which next MPI must be carried out: 08/12/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		