

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 27/09/2022	Report number: A/49876/22/09/54	Job no: 49876
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SOUTH SULTANATE OF OMAN		Address of premises at which the examination was made: NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p><u>CRANE HOOK (MAIN)</u></p> <p>Make : TADANO</p> <p>YOM : 2008</p> <p>Hook Serial No. : 2146125 (M7Z21)</p> <p>Owner ID No. : TS-703</p> <p>Crane Serial No. : 546514</p> <p>Reg. No. : 3962 YD</p> <p>Qty: 1no.</p>		
Date of Last MPI/ Cert No(If any): 14/10/2021; MP/47704/21/10/06		
<p>Result of the above test :</p> <p>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</p>		
Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 26/09/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

