

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 01.10.2025	Report number: AT5222.25.10.38	Job no: 5222
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment: <u>FIFTH WHEEL</u> Make: JOST Type: JSK 38C Serial No.: 2263141675 FLEET NO: TO 1000 REGESTRATION: 5607 YR Qty: 1 no		
Date of Last MPI/ Cert No (If any): 15/04/2025 (MP/1205/25/04/008)		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature: Anoop Thankachan		Latest date by which next MPI must be carried out: 30.03.2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		