



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---------------------------|
| Date of Through Examination: 10/03/2019 | Report number: MP/39039/19/03/159 | Job no: 39039 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN | Address of premises at which the examination was made: NIMR | |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others (TOP PLATE) | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: FIFTH WHEEL Make : JOST Size : 3½" Fleet No. : TS 207 Reg. No. : 8824 MD | | |
| Qty: 1no. | | |
| Date of Last MPI/ Cert No(If any): 13/04/2018 ; A/36961 | | |
| Details of tools/equipments used: Magnet (STS-LD-68) | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|---|------------------|--|
| Inspected by, Name & Signature : Qualification : ASNT L2 | Madhu Pillai | Latest date by which next MPI must be carried out: 09/03/2020 |
| Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com | | |