



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 08/07/2020	Report number: MP/43698/20/07/37	Job no: 43698
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: NIMR	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☐ Weldment areas ☒ Stress Areas ☐ Full Body ☐ Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>HOOK MPI FOR CRANE MAIN HOOK</u> Make : TADANO Model no. : GR 700 E Registration No. : 3457 YD Owner ID No. : TS 701 Main hook serial no. : 2146/34 Qty: 1no Date of Last MPI/ Cert No(If any): 09/07/202; MP/40196		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Madhu Pillai Qualification : ASNT L2		Latest date by which next MPI must be carried out: 07/07/2021
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

