



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---------------------------|
| Date of Inspection: 17/05/2022 | Report number: MP/48914/22/05/62 | Job no: 48914 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SOUTH SULTANATE OF OMAN | Address of premises at which the examination was made: NIMR | |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>CRANE HOOK</u> Make : GROVE Owners ID No. : PLM 1489 Reg. No. : 4436 YS Hook ID No. : 5086 Qty: 1 Date of Last MPI/ Cert No(If any): 31/05/2021; O/46722/20 | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|--|--|--|
| Inspected by, Name & Signature : Madhu Pillai Qualification : ASNT L2 | | Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | | |