



## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 13/06/2019	Report number: MP/40196/19/06/15	Job no: 40196
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made:  NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FIFTH WHEEL</u>		
Make : JOST		
Model No. : JSK 38 C		
Serial No. : 2063370339		
Reg. No. : 9154 DS		
Owner ID No. : TO 575		
Qty: 1no.		
Date of Last MPI/ Cert No( If any): 12/06/2018 ; O/37545		
Result of the above test :		
<b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature :  Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out:  12/06/2020
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		