

# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 17/05/2022	Report number: MP/48914/22/05/63	Job no: 48914
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SOUTH SULTANATE OF OMAN		Address of premises at which the examination was made:  NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>Fork Heel, Toe, Upper &amp; Bottom Hooks</u>		
Make : Caterpillar		
Reg. No. : 4767 MD		
ID No: PLM-427		
Fork Serial No: 2394252-L8 & 2438264-L8		
Qty: 1 PAIR		
Date of Last MPI/ Cert No( If any): 31/05/2021; O/46722/14		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out:  After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

