



الشركة الفنية لخدمات السلامة ش.م.م

SAFETY *technical* SERVICES CO. LTD.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 12-12-2018	Report number: A.39104.18.12.01	Job no: 39104
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: JIFNAIN	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ Top Surface Only ]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <b>FIFTH WHEEL</b>		
MAKE: JOST Fleet # PLM – 2007 Reg no.: 7804 ML		
Qty: 1nos		
Date of Last MPI/ Cert No( If any): NEW		
Result of the above test : <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : Qualification : ASNT L2	ANAZ 	Latest date by which next MPI must be carried out:
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		