

## MAGNETIC PARTICLE EXAMINATION REPORT

Date of Examination: <b>23/12/2025</b>		Report No: HITECH/TJN-2025-467/MT-140				
Client: <b>M/S.TRUCKOMAN EQUIPMENT RENTAL LLC, OMAN</b>		Contractor: <b>N/A</b>				
Starting Time of Inspection: <b>15.30 PM</b>		Opal LEIB Number: <b>KPFW373/117</b>				
Prime Mover Make / Trailer Type : <b>PRIME MOVER</b>		Chassis Number: <b>WMA34WZZ3DM619070</b>				
Project: <b>N/A</b>		Location: <b>KHAZZAN, SULTANATE OF OMAN</b>				
Procedure No. & Rev. No.: <b>HITECH-TPI-P-T-253-MT-14</b>		Referencing Code / Specification: <b>ASTM E709, AWS D1.1</b>				
Acceptance Criteria: <b>AWS D1.1</b>		Material: <b>N/A</b>				
Surface Condition: <b>Acceptable</b>		Surface Temperature: <b>Ambient</b>			PWHT: <b>N/A</b>	
Method: <input checked="" type="checkbox"/> Wet <input checked="" type="checkbox"/> Visible <input type="checkbox"/> Dry <input type="checkbox"/> Fluorescent		Technique: <input checked="" type="checkbox"/> Continuous <input type="checkbox"/> Residual			Magnetization: <input checked="" type="checkbox"/> Longitudinal <input type="checkbox"/> Circular	
Equipment Type: <b>Permanent Yoke</b>		Equipment Sr. No: <b>GAMMATEC 00810</b>			Cal. Validity: <b>Prior to Job</b>	
Type of Current: <b>N/A</b>		Lifting Power of Yoke: <b>18.1 Kg</b>		Sensitivity: <input checked="" type="checkbox"/> Burmah Strip <input type="checkbox"/> Pie Gauqe III Lines Visible		
Source of Light: <b>Day light</b>		Light Intensity: <b>≥ 1000 lux min</b>				
<b>Consumables: MAGNAFLUX</b>						
Cleaner: <b>MAGNAFLUX SKC-S</b>		White contrast: <b>MAGNAFLUX WCP-2</b>			Magnetic Ink: <b>MAGNAFLUX 7 HF</b>	
Batch No: <b>240706 BBE</b>		Batch No: <b>240702 BBE</b>			Batch No: <b>240705 BBE</b>	
Validity: <b>JULY-2027</b>		Validity: <b>JULY-2027</b>			Validity: <b>JULY-2027</b>	
Item Description/Line No./ Drawing No.	Weld No	Welder No	Size	Sch. / WT	Observation (Map or Record of Indication)	Result (Acc./Rej.)
<b>REGISTRATION NO &amp; OWNER ID NO: - 8883 HM / TO 2019 (PRIME MOVER 5<sup>TH</sup> WHEEL)</b>						
<b>FIFTH WHEEL</b> <b>MAKE: JOST</b> <b>TYPE: JSK 38 C</b> <b>SL NO: 14031971 63</b> <b>FOR KING PIN SIZE:3.5”</b>	<b>N/A</b>	<b>N/A</b>	<b>N/A</b>	<b>N/A</b>	<b>NO RELEVANT INDICATION OBSERVED</b>	<b>ACCEPTED</b>



"MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION"

LATEST DATE BY WHICH NEXT MPI MUST BE CARRIED OUT:		<b>23/12/2026</b>
Hi-Tech Inspection Services LLC	Contractor	Client
Signature:	Signature:	Signature:
		
Name: <b>LAKSHMANDAS.M</b>	Name:	Name:
Qualification: <b>ASNT NDT Level II</b>		
Date: <b>23/12/2025</b>	Date:	Date