

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 29/06/2021	Report number: V/46970/21/06/13	Job no: 46970
Name and Address of the Owner of the Equipment TRUCK OMAN (NORTH) SULTANATE OF OMAN	Address of premises at which the examination was made: ADAM	

Method: WET	Material: Carbon Steel	Test temperature: Ambient
Surface Condition: Acceptable	Equipment: Permanent magnet Yoke	

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others [TOP SURFACE]

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
------------------------------------	--

BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
-----------------------------------	---

Description and identification of the equipment:

FIFTH WHEEL

MAKE: JOST

SERIAL NO: 343208

OWNER ID: PLM - 1022

REG NO: 1659 HA

Qty: 1 no

Date of Last MPI/ Cert No(If any): N/A

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Vijeesh Ravi		Latest date by which next MPI must be carried out: 28/06/2021
--	---	--

Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com	
--	---

