الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/03/2021	**Report number:** O/46104/21/02/57	**Job no:** 46104

Name and Address of owner for whom the thorough examination was made: **TRUCK OMAN NORTH** **SULTANATE OF OMAN**	**Address of premises at which the examination was made:** **ADAM**

Method: WET **Material: Carbon Steel** **Test temperature: Ambient**
Surface Condition: Acceptable **Equipment: Permanent magnet Yoke**

Area Inspected (tick the appropriate box):

☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [TOP SURFACE ONLY]

WHITE CONTRAST PAINT: Magnavis WCP	**MAGNETISING METHOD: Wet suspension black ink**
BLACK MAGNETIC INK: Magnaflux 7HF	**ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1**

Description and identification of the equipment:

<u>FIFTH WHEEL</u>

Make : JOST

Type: JSK38C

Serial no; 10070595

Reg No: 9442 BA

Id no: TO 2030

Qty: 1no.

Date of Last MPI/ Cert No(If any): 5/03/2020; MP/42145/20/03/43

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION

Inspected by, Name & Signature : **Koshy Mathew** **Qualification : ASNT L2**	Koshy	**Latest date by which next MPI must be carried out:** **01/03/2022**
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED