




### MAGNETIC PARTICLE EXAMINATION REPORT

Date of Examination: <b>12/11/2025</b>				Report No: <b>HITECH/NJN-2025-467/MT-132</b>			
Client: <b>M/S.TRUCKOMAN EQUIPMENT RENTAL LLC, OMAN</b>				Contractor: <b>N/A</b>			
Starting Time of Inspection: <b>10.30 AM</b>				Opal LEIB Number: <b>KPFW373/012</b>			
Prime Mover Make / Trailer Type : <b>MAN</b>				Chassis Number: <b>WMA34WZZ9FP062716</b>			
Project: <b>N/A</b>				Location: <b>IBRI, SULTANATE OF OMAN</b>			
Procedure No. & Rev. No.: <b>HITIS/GEN/MT/01 REV.05</b>				Referencing Code / Specification: <b>ASTM E709, AWS D1.1</b>			
Acceptance Criteria: <b>AWS D1.1</b>				Material: <b>N/A</b>			
Surface Condition: <b>Acceptable</b>		Surface Temperature: <b>Ambient</b>		PWHT: <b>N/A</b>			
Method: <input checked="" type="checkbox"/> Wet <input checked="" type="checkbox"/> Visible <input type="checkbox"/> Dry <input type="checkbox"/> Fluorescent		Technique: <input checked="" type="checkbox"/> Continuous <input type="checkbox"/> Residual		Magnetization: <input checked="" type="checkbox"/> Longitudinal <input type="checkbox"/> Circular			
Equipment Type: <b>Permanent Yoke</b>		Equipment Sr. No: <b>GAMMATEC 00836</b>		Cal. Validity: <b>Prior to Job</b>			
Type of Current: <b>N/A</b>		Lifting Power of Yoke: <b>18.1 Kg</b>		Sensitivity: <input checked="" type="checkbox"/> Burnah Strip <input type="checkbox"/> Pie Gauge <b>III Lines Visible</b>			
Source of Light: <b>Day light</b>				Light Intensity: <b>≥ 1000 lux min</b>			
<b>Consumables: MAGNAFLUX</b>							
Cleaner: <b>MAGNAFLUX SKC-S</b>		White contrast: <b>MAGNAFLUX WCP-2</b>		Magnetic Ink: <b>MAGNAFLUX 7 HF</b>			
Batch No: <b>240706 BBE</b>		Batch No: <b>240702 BBE</b>		Batch No: <b>240705 BBE</b>			
Validity: <b>JULY-2027</b>		Validity: <b>JULY-2027</b>		Validity: <b>JULY-2027</b>			
Item Description/Line No./ Drawing No.	Weld No	Welder No	Size	Sch. / WT	Observation (Map or Record of Indication)		Result (Acc./Rej.)
<b>REGISTRATION NO &amp; OWNER ID NO: - 3747 HA / PLM-1026 (PRIME MOVER 5<sup>TH</sup> WHEEL)</b>							
<b>FIFTH WHEEL MAKE: JOST TYPE: JSK 38 C SL NO:1049552563</b>	<b>N/A</b>	<b>N/A</b>	<b>N/A</b>	<b>N/A</b>	<b>NO RELEVANT INDICATION OBSERVED</b>		<b>ACCEPTED</b>
<div style="display: flex; justify-content: space-around;">   </div>							
<b>"MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION"</b>							
<b>LATEST DATE BY WHICH NEXT MPI MUST BE CARRIED OUT:</b>						<b>12/11/2026</b>	
<b>Hi-Tech Inspection Services LLC</b>		<b>Contractor</b>			<b>Client</b>		
Signature:		Signature:			Signature:		
							
Name: <b>ANSON D'COSTA</b>		Name:			Name:		
Qualification: <b>ASNT NDT Level II</b>							
Date: <b>12/11/2025</b>		Date:			Date		